

Coastal Environments La Jolla, CA

www.coastalenvironments.com







- Lagoon Inlet Dynamics
  - Lagoon monitoring program
  - 1993 Flood
  - Inlet sedimentation
  - Inlet behavior
- Inlet Maintenance Plan
  - Initial and Periodic Maintenance
  - Excavation, public access and safety
  - Effect of artificial inlet opening on adjacent beaches
- Video Excavation Operation (Sep 2000)



#### Surveys and Measurements




#### San Dieguito Lagoon Summary of Surveys, 1992-94

# Surveys/Measurements Topographical Surveys Beach Profiles Water Levels & Flow Velocities Continuous Water Levels Water Quality Continuous Water Quality Directional Waves River Discharge Estimates Photographs Jan Mar May Jul Sep Nov Jan




#### 1993 San Dieguito River Discharge






#### **Established Transects**






#### Transects of Interest






#### Traverse TR2 Located at the Inlet Area





#### Traverse TR7 Located at West Channel

400



200

Distance Along Traverse (ft)

-4

-6


South



600


North

#### Traverse TR10 Located East Railway Bridge






#### Traverse TR11 Located East Railway Bridge






#### **Cross-Sections Changes**





#### Areas 1, 2 and 3






#### Sedimentation Rates Areas 1, 2 and 3

Area	Sedimentation Rate (yd³/month)		
	Mar-Apr 1993	May-Dec 1993	Jan-Sep 1994
AREA 1	6000	500	Small
AREA 2	2000	6000	Small
AREA 3	Small	Small	Up to 1000




#### Weak Outflow – Inlet 1992






Inlet Channel Migration, Feb-Mar 1992





#### Flood of 1993 causing Strong Flow – Inlet 1993






#### Stable Inlet – 1994










#### **Excavation Plan**



- Initial excavation
  - At start of project
  - Estimated by 45,000 yd<sup>3</sup>
- Periodic excavation
  - Every 8 months
  - 16,000 yd<sup>3</sup>




#### **Initial Excavation**






#### Periodic Excavation





#### **Estimated Excavated Volumes**



<sup>&</sup>lt;sup>a</sup> Estimates are based on the assumption that initial dredging will be carried out in early fall 1994.



<sup>&</sup>lt;sup>b</sup> Time interval in months from the date periodic dredging cycle starts (T<sub>o</sub>).







Number	Open Date	Close Date
1	23 Sep 2000	21 Nov 2001
2	4 Oct 2002	4 Nov 2002
3	5 Sep 2003	Still open



## Beach Response to SEP 2003 Artificial Inlet Opening



Profile Located Just South of Inlet



Control Profile Located 2,000 ft South of Inlet



### Excavation Operation – Sep 2000

